

## Potreba podvalov v ŽST Levice

Vyhýbka číslo	2,6	2,7	2,8	2,9	3,0	3,1	3,2	3,3	3,4	3,5	3,6	3,7	3,8	3,9	4,0	4,1	4,2	4,3	4,4	4,5	4,6	4,7	4,8	4,9	Sumár vyhýbky	
Levice v.č.2	4	3	3	3	4					3															17	
Levice v.č.5	5	2	2	2	5					3															17	
Levice v.č.3	4	3	3		3																				10	
Levice v.č.8	4	4	4	3	4					2															18	
Levice v.č.23	3				3						3	1	2											1	13	
Levice v.č.27ab	5	4	4	2	3																				14	
V. Kozmálovce v.č.3	4	3	3	4	4						2														17	
Kozárovce v.č.4	4	2	2		4							2													12	
Kozárovce v.č.15	3	2	2	3	3							3													14	
Kozárovce v.č.16	4	2	2	2	4								2												14	
																									0	
																									0	
																									0	
<b>Spolu</b>	<b>0</b>	<b>40</b>	<b>25</b>	<b>19</b>	<b>37</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>8</b>	<b>5</b>	<b>6</b>	<b>4</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>2</b>	<b>146</b>	
<b>Cena za MJ</b>	52,99	61,99	64,99	66,99	68,99	70,99	75,99	80,99	83,08	85,48	87,93	90,38	92,83	95,28	97,73	100,18	102,63	105,08	107,58	109,98					112,38	
<b>Cena spolu</b>	<b>0,00</b>	<b>2479,60</b>	<b>1624,75</b>	<b>1272,81</b>	<b>2552,53</b>	<b>0,00</b>	<b>0,00</b>	<b>0,00</b>	<b>0,00</b>	<b>683,84</b>	<b>439,65</b>	<b>542,28</b>	<b>371,32</b>	<b>0,00</b>	<b>0,00</b>	<b>0,00</b>	<b>0,00</b>	<b>0,00</b>	<b>0,00</b>	<b>0,00</b>	<b>0,00</b>	<b>0,00</b>	<b>0,00</b>	<b>224,76</b>	<b>10 191,64</b>	